



Model YL002685

Safety Instructions:

- Shut off the main electrical supply from the main fuse box/circuit breaker.
- Electric bulb should be centered inside the pendant shade, making sure it does not touch the outer sides.
- These instructions are provided for your safety. It is important that they are read carefully and completely before assembling fixture.

Warning:

- To reduce the risk of fire, electrical shock or personal injury, always turn off and unplug lamp and allow it to cool prior to replacing light bulb.
- Do not touch bulb when fixture is turned on. Do not look directly at lit bulb.
- Keep flammable materials away from lit bulb.

Pre-assembly:

- Remove all parts and hardware from box along with any plastic protective packaging.
- Do not discard any contents until after assembly is complete to avoid accidentally discarding small parts or hardware.
- For your safety and convenience, assembly by two people is recommended.

Assembly Instructions

SHUT OFF THE MAIN ELECTRICAL SUPPLY FROM THE MAIN FUSE BOX.

1. Mark the position of junction box crossbar's holes(middle) on your ceiling. Drill the ceiling holes for plastic anchors. Install the provided plastic anchors into the holes you've just drilled. Put the crimp studs inside-out on 4 outermost holes.

2. Mount the junction box crossbar with screws provided.
3. Stuff cable regulators into the holes on the canopy and lock tight with nuts.
4. Put cables through the cable regulators and determine the desired cable length.
5. Carefully inspect the fixture wires. The NEUTRAL FIXTURE WIRE is the silver wire inside the first plastic coat; The HOT FIXTURE WIRE is the silver wire inside the second plastic coat.
6. Make electrical connections. Sort out and connect the NEUTRAL FIXTURE WIRE to the NEUTRAL JUNCTION BOX WIRE. Fasten each together with a plastic wire connector. Connect the HOT FIXTURE WIRE to the HOT JUNCTION BOX WIRE. Fasten each together with a plastic wire connector. Be sure no wire strands are exposed. **DO NOT REVERSE THE HOT AND NEUTRAL CONNECTIONS OR SAFETY WILL BE COMPROMISED.**
- 7-8. Mount the fixture canopy to the junction box crossbar by covering the canopy over the crossbar where the screws are sticking out and lock into place with the nuts provided.
9. Thread lamp sockets through crystal glass globes and screw the metal rings onto the lamp sockets and fasten the lamp sockets with nuts.
10. Insert 110V G4 LED bulbs into the socket. Restore power to junction box and test fixture.